

15/12

SPLIT

DART AEROSPACE LTD	Work Order:	22468 4 C
Description: Arm Weldment	Part Number:	D3379-041
Dwg: D3379 Rev. A page 1	Qty:	20 100 4
		Page 1 of 1

Step	Location	Procedure	By	Date	Qty												
1	DC	Issue Traveler	4	05.02.16	100 4												
2	MFA	Assemble and weld using welding Jig DT8764 as per Dwg D3379 Pick: <table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>D3379-043</td> <td>Lever Assembly</td> <td>116634</td> </tr> <tr> <td>1</td> <td>D3379-1</td> <td>Support</td> <td>B22626</td> </tr> </tbody> </table> Identify as D3379-041	Qty	Part Number	Description	Batch	1	D3379-043	Lever Assembly	116634	1	D3379-1	Support	B22626	CPL	05/03/22	4 4
Qty	Part Number	Description	Batch														
1	D3379-043	Lever Assembly	116634														
1	D3379-1	Support	B22626														
3	QC5	Inspect work to Step 2	PD	05-03-23	4 4												
4	FP	Powder Coat Fire Red (Ref: 4.3.5.10) as per QSI 005 4.3 Mask holes	W	05 04 04	4												
5	QC3	Inspect Powder Coat	CY	05/04/04	4												
6	ST	Identify and Stock	CPL	05/04/04	4												
7	AC	Cost / part 54.15	Syc	05-04-06	4												
8	DC	Close W/O 54.15 Inspect Level 21	4	05.04.12	4												
Rev	Date	Change	Revised By	Approved													
A	05.02.03	New issue	KJ/JLM														

PRELIMINARY ISSUE

